

Tuglet To Do / Done List Follows at end

1. Head – replace both head and discharge lines – waiting for failure of existing
2. Wax all non-skid surfaces except hull
 - a. Stb – done 15,16
 - b. Port – done 15,16
 - c. Bow – done 15,16
 - d. Stern – done 15,16
3. Winterize water system
 - a. Hot water heater – done 15,16
 - b. Head – done 15,16
 - c. Head faucet – done 15,16
 - d. Galley faucet – done 15,16
 - e. Wash down - done 16
 - f. Prop shaft tube – self drains
 - g. Shower pan – done 15,16
 - h. Bilge pumps – done 15,16
5. Find air leak in funnel (smoke stack) air horn
 - i. Air horn reconnected to the dismay of many but still has a slow leak. Need to replace supply line.
9. Shower Drain – Alter slope due to bow down attitude, waterproof floor and bulkhead
14. Galley –
 - e. Make propane cylinder storage box ... done 15, needs new top
15. Aft – Add propane BBQ
 - b. Hose to propane supply may be required depending on use
17. Re-gasket external lockers
 - a. Total failure with new gaskets ... try again
24. Replace stern rails with s/s
25. Add Bimini and dodger, davits
27. Repair window gasket leaks
 - a. Door seals still leaking
28. Refinish wood side and aft doors, wood exterior trim, swim platform, funnel top
 - a. Side doors done 15,16
 - b. Side door frame done 15,16
 - c. Aft doors done 15,16
 - d. Aft door frame done 15,16
 - e. Bow hand rails done 15,16

- f. Swim platform done 15,16
 - g. Funnel top done 15,16
 - h. Hand rails top deck 15,16
 - i. Hand rails mid deck 15,16
29. Replace all cabinet doors
32. Engine supplies required
- a. Oil filter Napa 1806
 - b. Secondary Napa 3166
 - c. Racor Primary 2010SM-OR
 - d. 5 gal pink antifreeze
 - e. Diesel additive
 - f. 30 grade oil
 - g. ATF for transmission
 - h. Hydraulic fluid for steering
 - i. Impeller 1210-0001-P , Alternator belt
33. Galley/Cleaning supplies
- a. Oxyclean
 - b. Dish/Clothes detergent
 - c. Bounce, shout
 - d. Carpet cleaner
 - e. Upholstery cleaner
35. Things to consider for 2017
- a. Dinghy and motor – Li' Toot brought from Pilgrim
 - b. Espar heating
 - c. Bow thruster

THINGS done

4. Remove Bell (1890s locomotive)
- a. Bell teak supports unbolted
 - b. Clapper air supply disconnected
 - c. Bell removed destined for Craig's List
 - d. Gel coat repaired
 - e. Bell sold ... pays for new carpeting
5. Find air leak in funnel (smoke stack) air horn
- a. Air horn is a Kahlenber 116AMP, 631 hz, 124 db
 - b. Air horn air supply disconnected
 - c. Air horn actuator disconnected
 - d. Funnel removed
 - e. Leaking line to air horn replaced
 - f. Additional radar reflector added inside funnel
 - g. Gel coat repaired

- h. Replaced screw fasteners with inverted screws with top acorn nuts for easy removal of funnel
- 10. Pilot House – Label wiring, add additional AC circuits, add additional DC Buss bars, Stove 30 amp breaker
 - a. Added stove 30 amp breaker
 - b. Added new buss for dc +
- 11. Add solar panel and regulator – done 15, added 300 watts 16
- 12. Relocate and shorten Radar wiring -done
- 13. Electronics – Add BadBoy antenna, add AIS, fix Radar/Chart plotter, add GPS, AmpHour metre, CO and smoke detectors
 - a. Added GPS, AIS receiver and connected to radar/chart-plotter
 - b. Added Great lakes (Canadian) chart set to chart plotter
- 14. Galley – replace faucet, bar fridge with proper chest and range with propane, spice shelves, pressure cooker
 - a. Replaced faucet, removed fridge and range
 - b. Propane tank storage, regulator, solenoid, hoses needed ... done 2016
 - c. Factory plumbing has hose from cold water accumulator to galley cold water line then back to water heater inlet. Why? Rerouted 2016
 - d. Enlarged area for fridge
 - e. Make propane cylinder storage box ... done 15
- 15. Aft – Add propane BBQ
 - a. BBQ added
- 16. Batteries – Add 2 deep cycle and selector switch, inverter
- 17. Re-gasket external lockers
 - a. Total failure with new gaskets
- 18. Add storage bins for everything – done 15
- 19. Add trailer winch handle
 - a. Received handle did not fit ... bought 11/16 deep socket and will have it welded to handle
 - b. Replaced winch cable with 3 inch strap
- 20. Replace broken door hinges and locks
 - a. done
- 21. Add fid to counter top beside sink
 - a. done
- 22. Add name to bow, stern
 - a. done

23. Add logo to funnel
 - a. done
24. Replace bow rails with s/s – bow only 15
25. Add rod holders – done 16
26. Replace all lights with LEDs – anchor and interior – done 16
28. Refinish wood side and aft doors, wood exterior trim, swim platform, funnel top
 - a. Side doors done
 - b. Side door frame done
 - c. Aft doors done
 - d. Aft door frame done
 - e. Bow hand rails done
 - f. Swim platform done
 - g. Funnel top done
 - h. Hand rails top deck
 - i. Hand rails mid deck
30. Replace rug flooring
 - a. Need 92 sq ft of indoor/outdoor rug or 7 feet of standard 13 ft width – done
15
31. Replace Life Sling bag – done 15